


Figure 1. Cover of DMR binder. The binder is kept in the CHA offices.



TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page 1 of 15

Figure 2. July 2011 DMR, page 1.




Figure 3. July 2011 DMR, page 2.



Figure 4. Operator licenses in CHA office. Please note that Juan Mora no longer works for CHA. Tom Krasowski (IES) is currently under contract with CHA as their certified Wastewater Collections and Treatment operator.

ANALYTICAL LABORATORIES, INC.	
1804 NORTH 33RD STREET, BOISE, IDAHO 83703	
FLOWMETER CALIBRATION CERTIFICATION	
COMPANY:	
CALDWELL HOUSING AUTHORITY PO BOX 70 CALDWELL, ID 83605	
CALIBRATION DATE: OCTOBER 26, 2010	
EQUIPMENT:	
PRIMARY DEVICE: 60° V-NOTCH WEIR SECONDARY DEVICE: ULTRA SONIC FLOWMETER	
MANUFACTURER: SIGMA	
MODEL: 970	1823
SERIAL #: CLW	
AS FOUND SETTINGS/ EQUIPMENT DISTANCES:	18
LOCATION/SETTING AT ZERO FLOW: 0.12"	170
LOCATION/SETTING AT 100% FLOW: 6.00 FLOW SPAN: 5.00	
FLOW SPAN:5.88	
FINAL CALIBRATION SETTING/EQUIPMENT DISTANCES:	CX
LOCATION/SETTING AT ZERO FLOW: 0.00" LOCATION/SETTING AT 100% FLOW: 6.00	77
LOCATION/SETTING AT 100% FLOW: 6.00	**
FINAL FLOW SPAN: 6.00 114.5 GPM	蒙
COMMENTS: CALIBRATION .12" HIGH, ADJUSTED	200
	50
	102
Charle Vanes	
CHARLES DOWNEDS SERVICE DESCRIPTION	223
THE TOTAL OF THE SENTATIVE	1 数
	150
	122
	100

TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page **3** of **15**

Figure 5. Calibration certificate for ultrasonic flowmeter on effluent weir.





Figure 6. QAP cover.



TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page **4** of **15**

Figure 7. O&M Manual cover.




Figure 8. Contract laboratory QAP. Note that all analytical samples are collected by the contract laboratory.



TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page **5** of **15**

Figure 9. Looking east at Lagoon 1.



Figure 10. looking south at Lagoon 1. Aerator is in the shop being rebuilt.



Figure 11. Close-up of influent pipe into Lagoon 1 (looking east).



Figure 12. Looking south at Lagoon 2. Note duckweed growth at left of photo.



Figure 13. Looking southwest at Lagoon 2. Note that green color at aerators appears to be from duckweed.



Figure 14. Looking west along north berm of Lagoon 2.



Figure 15. Electrical panel between Lagoons 1 and 2 at north edge of site.



Figure 16. Parshall Flume meter box (concrete box at center of photo). Wiring runs along the ground surface through the burned area to the control panel located to the right (see Figure 15, above).



TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page **9** of **15**

Figure 17. Looking west along the south berm of Lagoon 2.



Figure 18. Looking southwest at Lagoon 3.



TRIM Record: 2011AGF2303


Inspection Date: 8/15/2011

Page **10** of **15**

Figure 19.Looking west along north berm of Lagoon 3.



Figure 20. Chlorine contact chamber (under tarp).



TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page **11** of **15**

Figure 21. Electrical panel in hypochlorite treatment building.



Figure 22. Hypochlorite solution storage tank (large white tank at right) and dispenser (at left).

TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page **12** of **15**



TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page **13** of **15**

Figure 23. Plant effluent weir. Ultrasonic flow meter is mounted above the v-notch weir shown.



TRIM Record: 2011AGF2303

Inspection Date: 8/15/2011

Page **14** of **15**

Figure 24. Composite sampler for effluent samples.



Figure 25. Outfall 001 discharge pipe (white PVC in weeds) to Sebree Canal.



Figure 26. Looking north from Outfall 001 to plant treatment building (left of center).